

## EXHIBIT A

Part 2-2 of 8

# REMOVAL ACTION STATUS

RCRA CORRECTIVE ACTION / CERCLA REMOVAL ACTION  
BEDFORD FACILITY, INDIANA

COMPLETED  
EXCAVATION WEST  
OF PEERLESS ROAD

PARCEL 40

PARCEL 400  
INVESTIGATION  
AREA

RESTORATION  
EAST OF  
PEERLESS ROAD

RESTORATION  
NORTH OF  
BROOMSAGE ROAD

SEEP AND SPRING  
WORK AREA

WEST PLANT AREA

Vault


COMPLETED COVER  
SYSTEM



# REMOVAL ACTION STATUS

RCRA CORRECTIVE ACTION / CERCLA REMOVAL ACTION

BEDFORD, INDIANA



# CREEK RESTORATION

## RCRA CORRECTIVE ACTION / CERCLA REMOVAL ACTION

BEDFORD COUNTY, PENNSYLVANIA



Restoration North of Broomsgage Road



© 2009 GM Corp.